

08-07-2019		Notification Overview		RISALITJ	Copy	Page 1 of 2
Notification	410143651			Notification Type	E1	
Subject Matter	EZ-ELEV	0010	Distribution Primary			
Description	REPLC DAMAGE PRI XARM POLE					
Reporter	HYATTBS		9:11:27 AM	Notification Date	04-29-2019	
Start Date	04-29-2019			End Date	10-29-2019	
Start time	7:23:00 PM			End time	11:59:00 PM	
Priority	EA	2	Priority 2			
Funct Location	OH-X6747E		POLE-DISTRIBUTION X6747E LOCATION			
Location Description	1469'W 369'S/O/N/E/C SEC 16 T1N R2W P/P					
City	RUNNING SP					
Thom. Guide	CASNBR-0-D1					
Equipment	201116129		POLE-DISTRIBUTION X6747E			
Circuit Name	ED-16222		SEYMOUR			

Order 902755781✓ Operation No. 0010 Pole Components OH NB REPR

Room 6031

Plant Section 231 D- Redlands

Sort field X6747E

PM Planner Group	231	Redlands S/C	Phone
Detail Position	0001		Text
Object Part	0020	Crossarm	Error Class
Damage	0022	Damaged/Broken	Assembly
Task	Replace		Work center 22D31 Redlands Default W C
Cause of Damage			
Cause Text			
Cause of Damage Code		Action Taken Code	

06/13/2019 14:19:37 PST CMSPiWSUSER (CMSPiWSUSER) Brandon Hyatt * 06/13/2019 14:18 * EOI, OFF CYCLE INSPECTION, EXTREME, Phase 2, Replace damaged crossarm

06/15/2019 09:11:46 PST G. Lomeli (LOMELIG1) Phone 909-274-3534 63534 EOI/OCI DATA SCRUB - NO CHANGES MADE, PICTURES ATTACHED. 06/17/2019 09:13:32 PST D. Lawson (LAWSONDF) Phone 760-218-2918 REPLACE XARMS.....CANNOT SEE DAMAGE ON PICS.....INSPECTORS VIEW BEST.....

NEED Helicopter

Comments

SCE Aircraft Operations Flight Request Form

Instructions: Please complete this form in its entirety and email to: airops@sce.com or fax to 909-974-4678. Once this form is received by Aircraft Operations, you will receive a response within 24 hours. For questions call SCE Aircraft Operations Dispatch at PAX 11676.

Requestor Information

Flight requested by:*	ERNIE FRANK
Department:*	DUSI
Pax:*	00000
Cell Number:*	661-808-9526
Email Address:*	ernief@dusi.com

SAP Accounting Number*

Flight Description

Please choose a mission type:

- | | | |
|---|---|---|
| ☐ Camera – HD/IR | ☐ Line String | ☐ Pole-set |
| ☐ Crew support | ☒ Passenger | ☐ Recon |
| ☒ External Load | ☐ Patrol | ☐ Training |
| ☒ HEC | ☐ Photo | ☐ Need more info, please contact |

Mission specific details (ex: Passenger name, pole size/weight, external load type, etc):

REPLACING 20' ARMS ON 2 H-STRUCTURES NO POLES WILL BE REPLACED

General Operating Location	34.178271, -117.092119, ONE POLE SOUTH
District	31-REDLANDS
LZ Coordinates (if known)	34.1894833, -117.092725
Pick-up location for passenger flights	SAME
Drop-off location for passenger flights	SAME

Date(s) for which service is requested	12/2/19
Time of Pick-up	0900
Approx. mission duration (if known)	6 HRS
Back-up date for mission (if known)	N/A

Authorizer	
Authorizer PAX and cell number	

**required information*

[Click to e-mail form](#)

For office use only

Date Received by Aircraft Operations: _____ Date Initial Contact Made: _____

Referred to contractor: ☐ No ☐ Yes, Date: _____ Company: _____

Follow up status: ☐ Week 1 _____

☐ Week 2 _____

☐ Week 3 _____

Legend



600 ft

23-1



Sailview Ln

Seymour Rd

Google Earth

© 2018 Google

Untitled Map

Write a description for your map.

Legend

-  34.178271,-117.092119
-  Running Springs

Google Earth

© 2018 Google



1000 ft

34.178271,-117.092119

view points

Seymour Rd