

D2-1594

09-24-2019	Notification Overview	KARLME	Copy	Page 1 of 1
Notification	409947940		Notification Type	E1
Subject Matter	EZ-ELEV 0010	Distribution Primary		
Description	REPLC DAMAGE PRI XARM POLE			
Reporter	GRUBERJM	7:05:32 AM	Notification Date	03-22-2019
Start Date	03-22-2019		End Date	09-22-2019
Start time	3:11:00 PM		End time	11:59:00 PM
Priority	EA 2	Priority 2		
Funct Location	OH-883267E	POLE-DISTRIBUTION 883267E LOCATION		
Location Description	P-P 10,090' N/O 101 HIWAY AT TAYLOR RANCH			
City	VENTURA			
Thom. Guide	CAVENT-470-H5			
Equipment	201919947	POLE-DISTRIBUTION 883267E		
Circuit Name	ED-07480	GRANDAD		

Order 902698013 Operation No. 0010 Pole Components OH NB REPR
Room 6039
Plant Section 239 D- Ventura
Sort field 883267E

PM Planner Group	239	Ventura S/C	Phone
Detail Position	0001		Text
Object Part	0020	Crossarm	Error Class
Damage	0022	Damaged/Broken	Assembly
Task	Replace		Work center 21N39 Ventura Default Work Cente
Cause of Damage			
Cause Text			
Cause of Damage Code		Action Taken Code	

03/23/2019 04:10:49 PST CMSPiWSUSER (CMSPiWSUSER) Jon Gruber * 03/23/2019 04:08 * EOI, OFF CYCLE INSPECTION, EXTREME, Phase 2, Timbers on H frame are split and deteriorated, need to replace
04/07/2019 08:09:18 PST Armando Fuentes III (FUENTEIA) Phone 562 209 0502 no pictures so im going off of the inspector....

Comments

09-24-2019		Notification Overview		KARLME	Copy	Page 1 of 1
Notification	408332180			Notification Type		E1
Subject Matter	EZ-ELEV	0010	Distribution Primary			
Description	INSTALL MISSING PRI HIGHSGN POLE					
Reporter	BRINTZN		7:08:00 AM	Notification Date	01-27-2017	
Start Date	01-27-2017			End Date		
Start time	9:41:46 AM			End time	12:00:00 AM	
Priority	EA	3	Priority 3			
Funct Location	OH-883267E		POLE-DISTRIBUTION 883267E LOCATION			
Location Description	P-P 10,090' N/O 101 HIWAY AT TAYLOR RANCH					
City	VENTURA					
Thom. Guide				CAVENT-470-H5		
Equipment	201919947		POLE-DISTRIBUTION 883267E			
Circuit Name						

Order		Operation No.
Room	6039	
Plant Section	239	D- Ventura
Sort field	883267E	

PM Planner Group	239	Ventura S/C	Phone
Detail Position	0001		Text
Object Part	0034	High Sign	Error Class
Damage	0048	Missing	Assembly
Task	Install		Work center 21N39
			Ventura Default Work Cente
Cause of Damage			
Cause Text			
Cause of Damage Code		Action Taken Code	

08/05/2019 12:30:04 PST M. Reed (REEDMM) Phone 805-654-7165 79165 Routed to Moorpark LDY

Comments
