


SCE Aircraft Operations Flight Request Form

Instructions: Please complete this form in its entirety and email to: <u>airops@sce.com</u> or fax to 909-974-4678. Once this form is received by Aircraft Operations, you will receive a response within 24 hours. For questions call SCE Aircraft Operations Dispatch at PAX 11676.


Requestor Information

Flight requested by:*				·
Department:*				
Pax:*				
Cell Number:*				
Email Address:*				
SAP Accounting Number*				
Dleage change a mission type.		Flight Description	<u>on</u>	
Please choose a mission type:				
□ Camera – HD/IR		Line String		Pole-set
□ Crew support		Passenger		Recon
□ External Load		Patrol		Training
□ HEC		Photo		Need more info, please co
General Operating Location District LZ Coordinates (if known) Pick-up location for passenger				
Drop-off location for passenge	er flights			
Date(s) for which service is re	anested			
Time of Pick-up	740000			
Approx. mission duration (if l	known)			
Back-up date for mission (if k				
Authorizer				
Authorizer PAX and cell num	ber			
*required information				
For office use only Date Received by Aircraft Operati Referred to contractor: □ No □ Y Follow up status: □ Week 1				Made:
□ Week 2 □ Week 3				
□ week 3				

06-08-2020	<u> </u>	Notification Over	rview RE	EDMM	Сору	Page 1 of 3	
Notification	410413114	· · ·			Notification Typ	e E1	
Subject Matter	EZ-ELEV	0010	Distribution P	rimary			
Description	•						
Reporter	SAMUELJ		1:58:37 PM		Notification Date	e 10-12-2019	
Start Date	10-12-2019				End Date	04-12-2020	
Start time	9:20:00 AM				End time	11:59:00 PM	
Priority	EA 2		Priority 2				
Funct Location	OH-831522E	Į.	POLE-DISTR	IBUTION	831522E LOCATION		
Location Descri	iption		SPRR PP 74	70'N E/S	W LINE RNCHO CANADA	A SN MIQUELIT	
City	VENTURA						
Thom. Guide							
Equipment	207436789		POLE-DISTR	BUTION	831522E		
Circuit Name	ED-07480		GRANDAD				
Order	902988947		Operation No	. 0010	114052E	· · · · · · · · · · · · · · · · · · ·	
Room	6039						
Plant Section	239		D- Ventura				
Sort field	831522E						
PM Planner Gro	oup 239	Ventura S/0	;	Phor	ne		
Detail Position	0001			Text			
Object Part	0032	Hardware/F	raming	Erro	r Class		
Damage	0022	Damaged/B	roken	Asse	embly		
Task	Repair			Worl	center 21N39	Ventura Default Work Cente	
Cause of Dam	age						
Cause Text							
Cause of Dama	age Code			Actio	on Taken Code [
10/15/2019 01:53:20 PST CMSPIWSUSER (CMSPIWSUSER) Jason Samuelson * 10/15/2019 01:52 * EOI/OFF CYCLE INSPECTION – AERIAL INSPECTION, EXTREME, Inspected 10/12/2019by SAMUELJ1, , Reviewed 10/14/2019by ALLENWT, Insulator shear ring backing out 12/02/2019 12:07:44 PST M. Moreno (MORENOMJ) Phone 805-654-7408 79408 FIELD CHECK IF BAD INSULATOR. REPLACE IF NEEDED. —————————————————————————————————							
Comments							
			·-				



Comments			
		··.	The second secon
** ·			



Comments	- V.	 	 	