

09-05-2019	Notification Overview		SIFUENAK	Copy	Page 1 of 2
Notification	410047382			Notification Type	E1
Subject Matter	EZ-ELEV	0010	Distribution Primary		
Description	REPLC DAMAGE PRI XARM POLE				
Reporter	DOLLRA	4:20:46 PM		Notification Date	02-05-2019
Start Date	02-05-2019			End Date	08-05-2019
Start time	12:33:00 PM			End time	11:59:00 PM
Priority	EA 2		Priority 2		
Funct Location	OH-1703142E		POLE-DISTRIBUTION 1703142E LOCATION		
Location Description	S. MTN RD P-P 300S. 8870 W/O BALCOM CYN RD				
City	SANTA PAULA				
Thom. Guide	CAVENT-464-H6				
Equipment	201863374		POLE-DISTRIBUTION 1703142E		
Circuit Name	ED-00990		BALCOM		

Order 902748081 Operation No. 0010 Pole Components OH NB REPR
Room 6039
Plant Section 239 D- Ventura
Sort field 1703142E

PM Planner Group	239	Ventura S/C	Phone
Detail Position	0001		Text
Object Part	0020	Crossarm	Error Class
Damage	0022	Damaged/Broken	Assembly
Task	Replace		Work center 21N39 Ventura Default Work Cente
Cause of Damage			
Cause Text			
Cause of Damage Code		Action Taken Code	

05/07/2019 03:23:39 PST CMSPiWSUSER (CMSPiWSUSER) Richard Doll * 05/07/2019 03:22 * OFF CYCLE INSPECTION, Deteriorated pole, arms splitting This structure has PASSED visual re-inspection by IPI
06/03/2019 06:28:03 PST R. Silva (SILVARM) Phone 805-208-1706 31210 Pole passed IPI visual inspection, no call on pole long shot picture does not show urgent condition requiring pole to be changed out at this time. This notification will be converted to replace damaged primary cross arm . Unable to see condition clearly due to low resolution dark picture. notification approved based on inspector comments arm split 06/17/2019 13:59:46 PST Janice Ashlee Spradley (SPRADLJ) ROUTED TO MOORPARK LDY

Comments

09-05-2019	Notification Overview		SIFUENAK	Copy	Page 1 of 1
Notification	400513217			Notification Type	E1
Subject Matter	EZ-ELEV	0010	Distribution Primary		
Description	REPLC DAMAGE PRI HIGHSGN POLE				
Reporter	HITCHKA	4:20:15 PM		Notification Date	11-26-2003
Start Date	11-27-2003			End Date	
Start time	8:00:00 AM			End time	12:00:00 AM
Priority	EA	3	Priority 3		
Funct Location	OH-1703142E		POLE-DISTRIBUTION 1703142E LOCATION		
Location Description	S. MTN RD P-P 300S. 8870 W/O BALCOM CYN RD				
City	SANTA PAULA				
Thom. Guide	CAVENT-464-H6				
Equipment	201863374		POLE-DISTRIBUTION 1703142E		
Circuit Name	ED-00990		BALCOM		

Order		Operation No.
Room	6039	
Plant Section	239	D- Ventura
Sort field	1703142E	

PM Planner Group	239	Ventura S/C	Phone	
Detail Position	0001		Text	2947830201
Object Part	0034	High Sign	Error Class	
Damage	0022	Damaged/Broken	Assembly	
Task	Replace		Work center	21N39 Ventura Default Work Cente
Cause of Damage				
Cause Text	T1R1			
Cause of Damage Code		Action Taken Code		

04/20/2010 00:23:43 LSMWR3COMMON (LSMWR3COMMON) HIGH SIGN BROKEN/MISSING DP ARRS 02089276
 1703142E - POLE Data Mopup: Priority Changed FROM 5 TO 3 06/17/2019 13:57:01 PST Janice Ashlee Spradley
 (SPRADLJ) ROUTED TO MOORPARK LDY

Comments
