

STA 9

01-09-2026	Notification Overview	RICHARSA	Copy	Page 1 of 4
Notification	414995206		Notification Type	E1
Subject Matter	EZ-ELEV 0010	Distribution Primary		
Description	REPAIR LOOSE PRI HWARE/FR POLE			
Reporter	BERNASTM	1:23:54 PM	Notification Date	11-03-2025
Start Date	11-03-2025		End Date	05-03-2026
Start time	3:07:47 PM		End time	3:07:47 PM
Priority	EA 2	Priority 2		
Funct Location	OH-1687708E	POLE-DISTRIBUTION 1687708E LOCATION		
Location Description	PP 2490 W/O 1250' S/O N/E COR SEC 10 T2N R4W			
City	?? VIEW/HIGHLAND			
Thom. Guide				
Equipment	207175890	POLE-DISTRIBUTION 1687708E		
Circuit Name	ED-13918	PENSTOCK		

Order 905050851 Operation No. 0010 1687708E
Room 6073
Plant Section 273 D- Victorville
Sort field 1687708E


PM Planner Group	273	Victorville S/C	Phone
Detail Position	0001		Text
Object Part	0032	Hardware/Framing	Error Class
Damage	0044	Loose	Assembly
Task	Repair		Work center 22D73 Victorville Default W C
Cause of Damage			
Cause Text			
Cause of Damage Code	<input type="text"/>	Action Taken Code	<input type="text"/>

11/03/2025 15:09:25 PST (ESAPOWSUSER) Tyler Mitchel Bernasconis * 11/03/2025 15:07 * 1687708E Pri cotter key backing out cold end Switching Center: Switching Center / Substation: Aqueduct 11/19/2025 13:30:32 PST (KELLYCM) Cotter pin will need to be resealed. 12/09/2025 08:01:59 PST (COLLAC) Phone +1 (760) 951-3210-13210 Released to C Ops 12.5.25 ----- 01/09/2026 13:20:40 PST (RICHARSA) Phone +1 (626) 543-7100-39100 Grouped under Task Order: 905050851

Comments



Comments



Comments



Comments

