

Flight Request

	Operations equest Form	
If you have any questions, please ca	all Aircraft Operations at : 909-974-4676	
- Requesto	or Information - Flight Request ID: FR00133	
Flight Requested by: Juan Rosas	SAP/TD Accounting No:	
	902942379-0140	
Requester Email: Juan.Rosas@SCE.Com	*Use commas to separate multiple numbers	
Office Number: (626) 366-3197 i.e. (xxx) xxx-xxxx	Cell Number: (626) 366-3197 i.e. (xxx) xxx-xxxx	
Department: Distribution		
- General Flig	ght Information -	
General Area:	District:	
South of Mount Wilson Observatory	MONROVIA	
Pick-up location:	Drop-off location:	
Mount Wilson		
LZ Coordinates (if known):		
34.2227408 -118.0627261		
Date for which service is requested:	Time of Pick-up:	
01/23/2020 ex. 01/01/2019	0800	
Note: Do not schedule outages until Air Ops has confirmed aircraft availability		
Approx. mission duration (if known):	Back-up mission date (if known):	
8HRS		
- Flight I	Description -	
Please choose a mission type:		
SCE F	Passenger(s): □	
Camera: OHD OIR	Heli-Saw:	
Crew Support: ☐	Passenger(s):	
External Load: 🗹	Patrol:☐ Training: ☐	
HEC: ☑	Photo:☐ Line Stringing:☐	
Pole Set: □		
	Approval attachment required ->>> Scanned from a Xerox Multifunction Prin	nter.pd
Note: Please remove the following characters from	the file title before attaching and Zip large files and folders with multiple files: # ~ / \: *?"<> %	
Please attach all Work Order Maps and Photos for Pole Sets		
Note: Please contact us at AirOps@sce.com or 909-974-4676 for any issues.		

Mission Specific Details	
Contract Crews to replace broken down guys on several H Structures South	n of Mount Wilson Observatory.
External Load - Approval must be obtained from:	
OU Requesting Manager or OSC	
Human External Cargo (HEC) - Approval must be obtained from:	Note;
OU Director or IC (unless Letter of Delegation is obtained)	Includes both SCE & Supplemental employees