

A2

REPLACE
CROSSARMS
AT 4044479E
TEE VEE 12KV



AREA SUBJECT TO DISPATCHERS BULLETIN NO. 322
WHEN A RED FLAG WARNING IS IN EFFECT, THE LINE OR LINE
SECTION WILL NOT BE RE-ENERGIZED FOLLOWING A LOCKOUT UNTIL
THE LINE OR LINE SECTION, SUBJECT TO BULLETIN 322 RESTRIC-
TION, HAS BEEN COMPLETELY PATROLED BETWEEN THE SOURCE
STATION OR STATIONS AND THE FAULT

50A
FI53077
4635411E

0207846
A 300
4782154E

1349514E

4665457E
PS
0667

1349499E
4665460E
BF53721

REMO
S
REG50
464849E

FOREST ROUTE 28508

200p

4044467E