

# 26-00304 Request Summary



<b>Requestor</b>	Eric W Bowers	<b>Request Date</b>	02/05/2026
<b>LAN ID</b>	ewba	<b>Operation Type</b>	Helicopter
<b>Phone</b>	(760) 253-7821	<b>Functional Area</b>	Telecomm / Ferry / Passenger Ferry
<b>Cell</b>	(760) 217-4374	<b>Emergency Work</b>	No
<b>Project Name</b>	Old Woman Mtn Refueling and repairs	<b>For Contractor</b>	No
<b>Vendor</b>	Guardian Helicopters		
<b>Region</b>	Central Valley		
<b>Division</b>	Kern		

## Work Dates

03/26/2026 BELL 407

<b>Approver</b>	Supervisor Thomas L Bradford (t6bx)	T6BX@PGE.COM	(C) (559) 580-0101
<b>Day-of Contact</b>	John Prince (jfpe)	(P) (661) 398-5773	(C) (661) 342-1637
<b>Supervisor</b>	Thomas L Bradford (t6bx)	(C)	

Is this work related to a storm or other event? No

## Daily Information

03/26/2026

**Asset Category:** LIGHT

**Asset Type:** BELL 407

### Locations

---

**07:30 A --- D - Pick Up** LZ PLS1 (pickup / refuel location) 34.66929 N <no headquarters> <no county> 2562 ft  
115.18215 W

1. Eric W Bowers	(EWBA Senior Telecommunications	225 lbs(C) (760)	(E) EWBA@PGE.COM
)	Technician	217-4374	
	TECH-0002: Y, Expires 11/25/2026		
2. Eric Olson	(E1OW Unassigned Telecommunications	200 lbs(C) (661)	(E) E1OW@PGE.COM
)	Tech	474-0845	
	TECH-0002: Y, Expires 04/16/2027		
3. Ivan Gonzalez	(I1G9) Unassigned Telecommunications	200 lbs(C) (661)	(E) I1G9@PGE.COM
	Tech	904-2282	
	TECH-0002: Y, Expires 04/16/2027		
4. Benjamin Zimmer		200 lbs(C) (951)	(E)
		897-3941	benjamin.zimmer@tuvsuo.com
	Government Employee: N Type: N/A Department: ---		
	Waiver: Y TECH-0002: Y		
	Emergency Contact: benjamin.zimmer@tuvsuo.com (C) (909) 677-7617		

Total Passenger Weight: 825.0 lbs

---

**--- A - Additional Stop**

## 26-00304 Request Summary

OLD WOMAN MTN MICROWAVE VAULT PG&E FACILITY	34.58966	Line #:	<no	<no	4036 ft
	N	OWM	headquarters>	county>	
	115.20688				
	W				

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Undergrounding	No	Hazardous Materials	Yes
Project		Special Equipment	Grapple - We have the sling/rigging onsite at OWM. We would need you to drop a hook that we could attach our rigging too for lifting the tanks. I will also attach a drag chute to the back of each tank to act a drag line to prevent the tank from spinning mid-flight.
Night Positioning Required	---		
Billing Number	70053565 100%		
Req. Notifications	Coordinating with Bureau of Land Management (BLM) for this operation to take place on 3/26/2026	Comments	<p>Operations Plan:</p> <ul style="list-style-type: none"> <li>-Water truck will wet down the LZ by 0730 and park next to corrals.</li> <li>-Water truck will re-wet the LZ as needed during the day.</li> <li>-Propane truck will stage a minimum of 300 feet from the LZ</li> <li>-Helicopter will arrive and land.</li> <li>-Pilot will conduct HeliOps Safety briefing.</li> </ul> <ol style="list-style-type: none"> <li>1. First flight to OWM will transport 3 PG&amp;E personnel. Helicopter will airlift pony tank #1 back to LZ for filling.</li> <li>2. Helicopter will airlift filled pony tank #1 from LZ back to OWM, pick up tank #2 and take it back to the LZ for filling. PG&amp;E will transfer fuel from pony tank #1 to main tank and prep pony tank #1 for pickup.</li> <li>3. Helicopter will airlift filled pony tank #2 from LZ to OWM, pick up tank #1 and take it back to the LZ for filling. PG&amp;E will transfer fuel from pony tank #2 to main tank.</li> <li>4. Helicopter will continue with steps 1 ?until main tank is at a minimum of 85% full.</li> <li>5. Once main tank is full the Helicopter will airlift filled pony tanks 1&amp;2 as needed to ensure we leave both pony tanks at OWM with 80% fuel in each.</li> </ol> <p>After dropping off final pony tank filled to 80%, helicopter will land at OWM and will transport personnel that have completed their work back</p>

## 26-00304 Request Summary

to the LZ. Helicopter will remain at the LZ only if all personnel have not completed their work at the OWM facility.

Propane truck will return home.

At the end of the workday, the helicopter will return to OWM to transport all

personnel/tools/materials back to LZ.

**Talk About #**  
**CC Recipients**

300

**Talk Group**

014

**Talk Radio #**

1868

IJC2@PGE.COM;JFPE@PGE.COM;T6BX@PGE.COM;TNMI@PGE.COM

# 26-00304 - March 2026

**Sunday**

**Monday**

**Tuesday**

**Wednesday**

**Thursday**

**Friday**

**Saturday**

1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26 <b>07:30 -15:30 N829DP</b> LZ PLS1 (pickup / refuel.. 34.66929 N 115.18215 W	27	28
29	30	31	1	2	3	4
5	6	7	8	9	10	11