

Aircraft Operations Flight Request Form



If you have any questions, please call Aircraft Operations at : 909-974-4676

- Requestor Information -

Flight Request ID: FR07996

FR_by SCE: Contractor:

OR

Air Ops Use Only:

Requester Name: Rigoberto Nieto

SAP/TD Accounting No:

905050851

**Use commas to separate multiple numbers*

Requester Email: rigoberto.nieto@sce.com

Cell Number: 5623559670

i.e. (xxx) xxx-xxxx

Office Number:

i.e. (xxx) xxx-xxxx

Company Name ASPLUNDH

Company_ContactName RIGO MORFIN

Company_Email RMORFIN@ASPLUNDH.COM

Company_PhoneNumber 5623559670

* Department

Distribution

- Approver Information -

Name: JEFF FLORY

Approver Title/Position (Director, Sr Manager, Etc): DESERT RCM

Email: JEFFREY.FLORY@SCE.COM

Mobile Number: 909-225-9319

2nd CONTACT

Name: NICK START

Company Name: ASPLUNDH

Email: NSTARK2@ASPLUNDH.COM

Mobile Number: 657-337-6257

- General Flight Information -

District:
VICTORVILLE

General Area (closest City or Town):
CRESTLINE

Flight Priority
N/A

* Valley Fever Mitigation Areas

 N/A

 Fresno

 Kern

 Kings

 Madera

 Merced

 Monterey

 San Joaquin

 San Luis Obispo

 Santa Barbara

 Tulare

 Ventura

Red List Customer Proximity

Off

Sensitive Area:

N/A

LZ Type of Property:

N/A

Passenger Pick-up Location (If applicable):

Passenger Drop-off Location (If applicable):

LZ Coordinates (if known):

34.273003, -117.294799

Requested Start Date:

6/23/2026

Requested End Date:

6/23/2026

Time of Pick-up

0800

Note: Flight Request(s) are not scheduled until Air Ops has sent confirmation notification

Approx. mission duration or number of days helicopter is required (if known):

4HRS

Hrs

Days

Weeks

M-F

Mon-Sat

7 days/week

Sat/Sun's Only

Other (explain in text)

Flight Description

Please choose a mission type:

SELECTION REQUIRED

SCE Passenger(s): Off

External Load: On

*** KMZ required for flight request to be processed ***

Crew Support: Off

Non-SCE Passenger(s): Off

Recon: Off

Pole Set: Off

Patrol: Off

Training: Off

HEC: On

*** KMZ required for flight request to be processed ***

Imaging:

Line Stringing: Off

Line Vue: Off

LiDAR: Off

Approval Attachment Required ->>>



905050851 6-23-26.kmz



Re_ (External)_Fw_ 905050851 HELO SUPPORT 6-23-26 - Rigo Morfin - Outlook.j

Note: Please remove the following characters from the file title before attaching and Zip large files and folders with multiple files: # ~/\: * ? " < > | %

Please attach all Work Order Maps and Photos for Pole Sets

Mission Specific Details

FLYING IN TOOLS & CREW TO MAKE SIMPLE REPAIRS TO POLES

External Load - Approval must be obtained from:

OU Requesting Manager or OSC

Human External Cargo (HEC) - Approval must be obtained from:

Note:

OU Director or IC (unless Letter of Delegation is obtained)

Includes both SCE & Supplemental employees

- Circuit Information -

1. Circuit Name:	PENSTOCK	Voltage:	12KV
2. Circuit Name:		Voltage:	
3. Circuit Name:		Voltage:	
4. Circuit Name:		Voltage:	
5. Circuit Name:		Voltage:	

[Click here to add more](#)

- Flight Request HEC Justification -

Environmental restrictions/impact
● Additional notes/documentation needed

Tower Infrastructure operations
● Additional notes needed

Mid-span operations
● Automatic approval

Hazardous topography
● Additional notes needed

No access within reasonable walking distance
● Additional notes needed

operational efficiency
● Additional notes needed

Notes

FLYING IN TOOLS & CREW TO MAKE SIMPLE REPAIRS TO POLES

- External Load Information -

Equipment/Material	Weight(lbs)	GPS Coordinates (Lat/L ong):	Elevation:
TOOL BASKET	700	34.276944, -117.285535	4239

Equipment/Material	Weight(lbs)	GPS Coordinates (Lat/L ong):	Elevation:
--------------------	-------------	------------------------------	------------

Equipment/Material

Weight(lbs)

GPS Coordinates (Lat/Long):

Elevation:

Equipment/Material

Weight(lbs)

GPS Coordinates (Lat/Long):

Elevation:

Equipment/Material

Weight(lbs)

GPS Coordinates (Lat/Long):

Elevation: