

21-01078 Request Summary



Requestor	Charles A Hengehold Jr.	Request Date	05/25/2021
LAN ID	c4h2	Work Type	Ferry
Phone	(925) 324-6073	Ferry Type	Special Project
Cell	(925) 324-6073	For Contractor	Yes
LOB	Other		Aethon
Vendor	Guardian Helicopters		

Work Dates

06/01/2021 - 06/05/2021 AS350B2

06/07/2021 - 06/10/2021 AS350B2

Approver Supervisor Charles A Hengehold Jr. (C4h2) C4H2@pge.com (C) (925) 324-6073

Daily Information

06/01/2021

Reason for Request in Less than 10 Days:

Other

Reason for Request in Less than 10 Days Explained:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
------------------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
Government Employee Type: N/A					
Department: ---					
(E) phelman@aethonaerial.com					
Emerg.: Andy Hengehold (925) 324-6073					

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

SYSTEM INTEGRATION & GROUND TESTING	<no lat/lon>	<no headquarters>
-------------------------------------	--------------	-------------------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

21-01078 Request Summary

28 May: System arrives in Fillmore

NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System
Troubleshooting / Data Processing

9 Jun: Demobilization / Pack
System

10 Jun: Ship system back to
Canada

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 Request Summary

06/02/2021

Reason for Request in Less than 10 Days:

Other

Reason for Request in Less than 10 Days Explained:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
-----------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
Government Employee Type: N/A					
Department: ---					
(E) phelman@aethonaerial.com					
Emerg.: Andy Hengehold (925) 324-6073					

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

TEST FLIGHT	<no lat/lon>	<no headquarters>	264 ft
-------------	--------------	-------------------	--------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

28 May: System arrives in Fillmore
NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System

Troubleshooting / Data Processing

9 Jun: Demobilization / Pack

System

10 Jun: Ship system back to

21-01078 Request Summary

Canada

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 Request Summary

06/03/2021 - 06/04/2021

Reason for Request in Less than 10 Days:

Other

Reason for Request in Less than 10 Days Explained:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
-----------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
Government Employee Type: N/A					
Department: ---					
(E) phelman@aethonaerial.com					
Emerg.: Andy Hengehold (925) 324-6073					

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

ETL CAPTURE TEST	<no lat/lon>	<no headquarters>
------------------	--------------	-------------------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

28 May: System arrives in Fillmore
NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System

Troubleshooting / Data Processing

9 Jun: Demobilization / Pack

System

10 Jun: Ship system back to

21-01078 Request Summary

Canada

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 Request Summary

06/05/2021

06/07/2021 - 06/08/2021

Reason for Request in Less than 10 Days:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
-----------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
		Government Employee Type: N/A			
		Department: ---			
		(E) phelman@aethonaerial.com			
		Emerg.: Andy Hengehold (925) 324-6073			

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

SYSTEM TROUBLESHOOTING	<no lat/lon>	<no headquarters>
------------------------	--------------	-------------------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

28 May: System arrives in Fillmore
NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System

Troubleshooting / Data Processing

9 Jun: Demobilization / Pack
System

10 Jun: Ship system back to
Canada

21-01078 Request Summary

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 Request Summary

06/09/2021

Reason for Request in Less than 10 Days:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
-----------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
Government Employee Type: N/A					
Department: ---					
(E) phelman@aethonaerial.com					
Emerg.: Andy Hengehold (925) 324-6073					

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

DEMOBILIZATION / PACK SYSTEM	<no lat/lon>	<no headquarters>
------------------------------	--------------	-------------------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

28 May: System arrives in Fillmore
NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System

Troubleshooting / Data Processing

9 Jun: Demobilization / Pack

System

10 Jun: Ship system back to

Canada

21-01078 Request Summary

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 Request Summary

06/10/2021

Reason for Request in Less than 10 Days:

Asset Category: LIGHT

Asset Type: AS350B2

Locations

08:00 - Pick Up	67 D St, Fillmore, CA 93015	34 23.47'N 118 55.95'W	<no headquarters>	<no county>
-----------------	-----------------------------	---------------------------	-------------------	-------------

Dust/Snow Mitigation Plan: Surface is composed of asphalt, concrete or gravel.

1. Peter Helman	250 lbs	(C) (509) 995-9635	TECH-0002: Y	Waiver: Y	Govt Emp: N
		Government Employee Type: N/A			
		Department: ---			
		(E) phelman@aethonaerial.com			
		Emerg.: Andy Hengehold (925) 324-6073			

Total Passenger Weight: 250.0 lbs

--- - Additional Stop

SHIP SYSTEM BACK TO CANADA	<no lat/lon>	<no headquarters>
----------------------------	--------------	-------------------

Dust/Snow Mitigation Plan: ---

Same passengers as previous

Est. Use Hours	8.00	Vendor	Guardian Helicopters
Contract	---	Over Water	No
Special Equipment	Testing Aethon's AIC 18 System	Billing Number	8199137 100%
Comments	Request to use GHI due to Guardian's familiarity with Aethon's Equipment.	Req. Notifications	---

AIC 18 TEST PLAN / SCHEDULE
(1-10 Jun based on weather / system results)

28 May: System arrives in Fillmore
NLT

1 Jun: System Integration and
Ground Testing

2 Jun: Test Flight

3 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

4 Jun: ETL Capture Test (Current
Profile / Guy Wire Profile)

5 Jun: Weather Day / System
Troubleshooting / Data Processing

6 Jun: No-Fly

7 Jun: Weather Day / System
Troubleshooting / Data Processing

8 Jun: Weather Day / System

Troubleshooting / Data Processing

9 Jun: Demobilization / Pack

System

10 Jun: Ship system back to

Canada

21-01078 Request Summary

Note: If data capture and data processing is completed 5 June, the system could be removed from the aircraft that day or shortly after returning it back to support other efforts.

21-01078 - June 2021

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
30	31	1 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	2 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	3 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	4 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	5 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W
6	7 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	8 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	9 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	10 08:00 -16:00 AS350B2 67 D St, Fillmore, CA.. 34 23.47'N 118 55.95'W	11	12
13	14	15	16	17	18	19
20	21	22	23	24	25	26
27	28	29	30	1	2	3
4	5	6	7	8	9	10